UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,731,098 B1

DATED

: May 4, 2004

INVENTOR(S) : Hintz et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1,

Line 11, "alternator particular" should be -- alternator. In particular --.

Line 62, "port and" should be -- port 501 and --.

Signed and Sealed this

Page 1 of 1

First Day of February, 2005

JON W. DUDAS Director of the United States Patent and Trademark Office